## **INSPECTION REPORT**

INST ECHION NEI ONI			
PERMIT NUMBER:	BP-15-00907	OWNER'S NAME:	HANSEN
DATE:	10/25/2016	TYPE:	Re-inspection
TIME STARTED:	11:46 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	17-18-08059-0001		
<ol> <li>Truss bracing on garage trussses</li> <li>Headers missing at master bed door and master closet door</li> <li>Clip top of stair stringers to LVL</li> <li>Strap beam to top plate at dining room beam north end</li> <li>Letter in works for approval of 2x8 at 24" oc in bonus dormers</li> </ol> INSTRUCTIONS: Ok to insulate			
NEXT INSPECTION: Insulation			
RE-INSPECTION FEE			\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
OUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING F-MAIL			

ADDRESS: <u>iessica.contratto</u> @co.kittitas.wa.us

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506