INSPECTION REPORT

PERMIT NUMBER:	BP-15-00939	OWNER'S NAME:	RHODES
DATE:	6/21/2016	TYPE:	Mechanical
TIME STARTED:	10:31 AM	INSPECTOR:	Justin Bennett
MAP NUMBER:	20-15-34068-0007		
 Fireplace rough in Ok Gas @ 30#/15 mins - Ok Terminate flex on exhaust fan in powder room Mechanical rough in Ok 			
INSTRUCTIONS: Verify powder room exhaust duct @ framing			
NEXT INSPECTION: Framing			
RE-INSPECTION FEE			\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL			

INSPECTION REQUEST LINE: 509-962-7694

ADDRESS:

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506

iustin.bennett @co.kittitas.wa.us