INSPECTION REPORT

PERMIT NUMBER: BP-15-00962 OWNER'S NAME: MOFFAT

DATE:		12/29/2015	TYPE:	Gas piping
TIME STARTED:		10:30 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:		18-19-31030-0010		
	1. Gas pipin	g at 27#-ok		
INSTRUCTIONS: Complete furnace and water heater installation				
NEXT INSPECTION: Final				
RE-INSPECTION FEE DUE? VES \$				
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION				
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:				
iessica.contratto @co.kittitas.wa.us				
• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506				