## **INSPECTION REPORT**

	DD 40 00404		LIODOE CANDON DAN
PERMIT NUMBER:	BP-16-00121	OWNER'S NAME:	HORSE CANYON RAN
DATE:	4/11/2016	TYPE:	Gas piping
TIME STARTED:	11:19 AM	INSPECTOR:	Justin Bennett
MAP NUMBER:	20-17-32040-0004		
1. Corrections O 2. Fire pit gas @ 3. Ok to cover	ok 2 15#/15 mins - Ok		
INSTRUCTIONS: Ok to cover			
NEXT INSPECTION:	Final		
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL  ADDRESS: justin.bennett @co.kittitas.wa.us			
1910-1910-1910-1910-1910-1910-1910-1910			

**INSPECTION REQUEST LINE: 509-962-7694** 

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506