## **INSPECTION REPORT**

PERMIT NUMBER:	BP-16-00192	OWNER'S NAME:	NORTHLAND INVESTI
DATE:	6/9/2016	TYPE:	Mechanical
TIME STARTED:	11:41 AM	INSPECTOR:	Amber Green
MAP NUMBER:	20-15-26063-0005		
Not all ducts insulated in crawl space.			
2. Rough-In Fireplace not complete.			
3. Gasline (17#/15min) - OK			
4. Blue address plate must be posted prior to next inspection.			
5. Please make sure you are providing the gate code at each inspection.			
INSTRUCTIONS: Complete duct insulation. Install fireplace.			
NEXT INSPECTION: Plumbing/Re-Mechanical			
RE-INSPECTION FEE I	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
amber.green @co.kittitas.wa.us			
■ INSPECTION REQUEST LINE: <u>www.co.kittitas.wa.us/cds/request.asp</u> or 509-962-7694 ■  411 N. Ruby Street, Suite 2. Ellensburg, WA 98926 ■ Main Office Line: 509-962-7506			