## **INSPECTION REPORT**

PERMIT NUMBER:	BP-16-00232	OWNER'S NAME:	BACK COUNTRY
DATE:	8/9/2016	TYPE:	Insulation
TIME STARTED:	3:21 PM	INSPECTOR:	Justin Bennett
MAP NUMBER:	19-15-07061-0010		
<ol> <li>Insulation touching chimney @ overframing - provide required clearance</li> <li>Vapor barrier does not got to sill @ Master shower pan - repair vapor barrier</li> </ol>			
INSTRUCTIONS: Make corrections above/Ok to cover areas without corrections/DO NOT COVER AFFECTED AREAS FOR RE-INSPECTION			
NEXT INSPECTION: Re-Inspection			
RE-INSPECTION FEE DUE? VES \$			
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL  ADDRESS: <u>justin.bennett</u> @co.kittitas.wa.us			
INSPECTION REQUEST LINE: 509-962-7694  http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx			

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506