INSPECTION REPORT

PERMIT NUMBER:	BP-16-00249	OWNER'S NAME:	COVEY
DATE:	4/21/2017	TYPE:	Mechanical and plumbir
TIME STARTED:	1:12 PM	INSPECTOR:	Justin Bennett
MAP NUMBER:	19-15-08051-0004		
1. DWV @ 5#/15 mins - Ok 2. Supply @ 70#/15 mins - Ok 3. Plumbing RI Ok 4. Exhaust fans not terminated 5. HVAC SA/RA Ok 6. Gas @ 16#/15 mins - Ok INSTRUCTIONS: Complete EF duct installation/Verify @ Framing			
NEXT INSPECTION:	Framing		
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
	QUESTIONS? PLEASE CONTACT THE ADDRESS:	NSPECTOR AT THE FO	

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506