## **INSPECTION REPORT**

INSPECTION REPORT			
PERMIT NUMBER:	BP-16-00322	OWNER'S NAME:	SHAW
DATE:	6/10/2016	TYPE:	Stove or fireplace
TIME STARTED:	9:50 AM	INSPECTOR:	Justin Bennett
MAP NUMBER:	18-19-08030-0025		
<ol> <li>Fireplace Rough In Ok</li> <li>Install combustion air below fire box Due to location being outside in a covered patio, no combustion air requirement below firebox need. MF 6/14/16</li> </ol>			
INSTRUCTIONS: Confirm combustion air @ Final Not required. OK to final.			
NEXT INSPECTION: Final Not required. Final complete.			
RE-INSPECTION FEE DUE?			
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL  ADDRESS: <u>justin.bennett</u> @co.kittitas.wa.us			

**INSPECTION REQUEST LINE: 509-962-7694** 

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506