INSPECTION REPORT

PERMIT NUMBER:	BP-16-00324	OWNER'S NAME:	FITTERER
DATE:	5/9/2017	TYPE:	Stove or fireplace
TIME STARTED:	3:45 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	21-18-31000-0001		
 Fireplace rough-in on main floor ok Chimney clearances and draftstop ok Fresh air and cooling ducts ok Basement fresh air under slab to outside Basement chimney rough-in ok 			
INSTRUCTIONS:			
NEXT INSPECTION:			
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL			
ADDRESS: <u>iessica.contratto</u> @co.kittitas.wa.us			
INSPECTION REQUEST LINE: 509-962-7694			
http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx			
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 ● Main Office Line: 509-962-7506			