INSPECTION REPORT

PERMIT NUMBER:	BP-16-00340	OWNER'S NAME:	KELLEY
DATE:	10/27/2016	TYPE:	Framing
TIME STARTED:	3:12 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	18-17-36051-0007		
 Plumbing/Mechanical inspection performed DWV at 7#-ok H2o at 50#-ok Gas not installed yet Fireplace not installed yet 			
INSTRUCTIONS:			
NEXT INSPECTION:	Function		
TEXT INST LETTON	Framing		
RE-INSPECTION FEE DUE? VES \$ IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL			
ADDRESS: <u>iessica.contratto</u> @co.kittitas.wa.us			
INSPECTION REQUEST LINE: 509-962-7694			
http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx			
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506			