## **INSPECTION REPORT**

OWNER'S NAME: KELLEY

PERMIT NUMBER: BP-16-00340

DATE:	3/22/2017	TYPE:	Final		
TIME STARTED:	9:47 AM	INSPECTOR:	Jessica Contratto		
MAP NUMBER:	18-17-36051-0007				
<ol> <li>Seal all penetrations in garage fire separation. Furnace, duct, lineset, water lines, vac lines</li> <li>Install condensate line for cooling coil when outdoor unit is eventually installed. Complete lineset insulation near coil</li> <li>Door from residence to garage to be self closing/latching</li> <li>Complete or make safe electrical in laundry</li> <li>Laundry fan not functioning. Breaker off?</li> <li>Gas range not functional</li> <li>Complete electrical under kitchen sink</li> <li>Windows in great room less than 18" above walking surface considered hazardous location per IRC R308.4.3 Safety glazing or approved safety coating required</li> <li>Outdoor fireplace not operational</li> <li>Seal gas line at meter penetration at foundation</li> <li>Secure hose bibb near crawl access</li> <li>Provide blower door test results</li> <li>Septic not approved through Health dept</li> </ol>					
INSTRUCTIONS: Complete/address above corrections					
NEXT INSPECTION: Re-inspect					
RE-INSPECTION FEE DUE? VES \$					
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION					
	QUESTIONS? PLEASE CONTACT THE II				
	ADDRESS:ie	essica.contratto @	co.kittitas.wa.us		
INSPECTION REQUEST LINE: 509-962-7694					

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506

## **INSPECTION REPORT**

PERMIT NUMBER:	BP-16-00340	OWNER'S NAME:	KELLEY		
DATE:	3/22/2017	TYPE:	Final		
TIME STARTED:	9:47 AM	INSPECTOR:	Jessica Contratto		
MAP NUMBER:	18-17-36051-0007				
Page 2					
<ul> <li>14. Approved plans not on site. Unable to verify use of small garage area. Garage space cannot be heating using unit that heats living space. Must be separate heat source</li> <li>15. Energy credits requirements unable to be verified without approved plans. Current available credits are high effficiency gas furnace and efficient water heating</li> <li>16. Whole house ventilation system installed on duct system-ok</li> <li>17. Provide means to access attics for insulation inspection</li> <li>18. Complete WUIC inspection from Fire Marshal</li> </ul>					
INSTRUCTIONS: Complete/address above corrections					
NEXT INSPECTION: Re-inspect					
RE-INSPECTION FEE		DAID DDIGG TO CO!!	\$		
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION  QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL					
ADDRESS: <u>iessica.contratto</u> @co.kittitas.wa.us					

**INSPECTION REQUEST LINE: 509-962-7694** 

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506