INSPECTION REPORT

INST ECTION NET ON			
PERMIT NUMBER:	BP-16-00463	OWNER'S NAME:	ROSE
DATE:	3/17/2017	TYPE:	Mechanical and plumbir
TIME STARTED:	2:31 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	17-23-19010-0004		
 Gas at 30#-ok DWV at 8#/15-ok H20 at 80#/15-ok Exhaust duct ok Supply/return duct ok Trusses ok. Truss screws used Unable to locate complete set of full size approved plans. Complete all electrical wiring before framing inspection Fireplace rough in ok 			
INSTRUCTIONS: Provide approved plans for framing inspection			
NEXT INSPECTION: Framing			
RE-INSPECTION FEE			\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS: <u>iessica.contratto</u> @co.kittitas.wa.us			

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506