INSPECTION REPORT

PERMIT NUMBER:	BP-16-00501	OWNER'S NAME:	COSTA
DATE:	5/1/2017	TYPE:	Final
TIME STARTED:	2:43 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	18-19-13000-0001		
1. Seal all penetrations in fire separation at garage wall. Water heater electrical, duct into ceiling, etc 2. Seal drywall to roof sheathing and seal ridge vent gap at roof to drywall. Seal gaps to framing at walls around paerimeter of drwall. Install drywall corner above mechanical area in garage. Complete missing drywall piece at truss over garage door 3. Plumbing ok 4. Energy credits ok INSTRUCTIONS: Complete fire separation sealing NEXT INSPECTIONS: Pagingsort			
Re-inspect			
RE-INSPECTION FEE			\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS: iessica contratto @co.kittitas.wa.us			

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506