INSPECTION REPORT

PERMIT NUMBER:	BP-16-00535	OWNER'S NAME:	MURATA
DATE:	7/13/2017	TYPE:	Mechanical and plumbir
TIME STARTED:	10:15 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	17-19-32030-0013		
 Gas at 22#-ok DWV at 7#-ok H20 at 75#-ok Mini split rough ins ok Exhaust duct ok 			
INSTRUCTIONS:			
NEXT INSPECTION:	Framing/insulation		
RE-INSPECTION FEE DUE? V NO YES \$ IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS: <u>iessica.contratto</u> @co.kittitas.wa.us			
INSPECTION REQUEST LINE: 509-962-7694 http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506			