



KITITITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

## INSPECTION REPORT

PERMIT NUMBER: BP-16-00621

OWNER'S NAME: TROUT

DATE: 6/14/2017

TYPE: Framing

TIME STARTED: 12:35 PM

INSPECTOR: Jessica Contratto

MAP NUMBER: 20-15-29051-0084

1. Strap across top plate breaks at beam penetrations in mud room exterior wall
2. Safety glazing in upstairs bath with walk-in shower
3. Verify detail 2/D3 required at upstairs P1-3" chimney chase wall. Circled on roof framing plan
4. Truss brace B02 truss in master bedroom/bath

INSTRUCTIONS: Complete above, see at insulaton

NEXT INSPECTION: Insulation

RE-INSPECTION FEE DUE?  NO  YES \$ \_\_\_\_\_

**IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION**

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL  
ADDRESS: \_\_\_\_\_ [jessica.contratto @co.kittitas.wa.us](mailto:jessica.contratto@co.kittitas.wa.us)

**INSPECTION REQUEST LINE: 509-962-7694**

<http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx>

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506