INSPECTION REPORT

PERMIT NUMBER: BP-16-00631 OWNER'S NAME: HERIC

DATE:	11/10/2016	TYPE:	Gas piping
TIME STARTED:	3:37 PM	INSPECTOR:	Amber Green
MAP NUMBER:	21-13-17050-0004		
1. Gasline (30#/15) - OK			
INSTRUCTIONS: Install unit for inspection prior to cover.			
NEXT INSPECTION: Fireplace Rough-In			
RE-INSPECTION FEE DUE? VES \$			
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
amber.green @co.kittitas.wa.us			
 INSPECTION REQUEST LINE: <u>www.co.kittitas.wa.us/cds/request.asp</u> or 509-962-7694 ◆ 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 ◆ Main Office Line: 509-962-7506 			
.11 may see edy same 1, the most of the main of the third source and source the source of the main of the third source of the main of			