



KITITITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER: BP-16-00692 OWNER'S NAME: MINERS CAMP
DATE: 1/25/2017 TYPE: Exterior shear
TIME STARTED: 12:23 PM INSPECTOR: Justin Bennett
MAP NUMBER: 20-15-19060-0001

1. Tighten up nailing in (3) locations (clouded on dwgs)
2. Complete strap (1) @ front window per 3/D3
3. Interior Shear not inspected - revision forth coming
4. NOTE: Interior Shear to be inspected @ Framing

INSTRUCTIONS: Complete above/Once complete Ok to cover

NEXT INSPECTION: Plumb/Mech

RE-INSPECTION FEE DUE? NO YES \$ _____

IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL
ADDRESS: _____ [justin.bennett @co.kittitas.wa.us](mailto:justin.bennett@co.kittitas.wa.us)

INSPECTION REQUEST LINE: 509-962-7694

<http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx>

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506