



KITITITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER: BP-16-00700

OWNER'S NAME: STYSKEL

DATE: 4/17/2017

TYPE: Exterior shear

TIME STARTED: 11:22 AM

INSPECTOR: Justin Bennett

MAP NUMBER: 20-15-29051-0120

1. Straps missing @ Trash Room
2. Exterior nailing Ok
3. Interior nailing Ok
4. Flr to Flr straps in progress in Bonus Rm

INSTRUCTIONS:

NEXT INSPECTION: Plumb/Mech

RE-INSPECTION FEE DUE? NO YES \$ _____

IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL
ADDRESS: _____ justin.bennett@co.kittitas.wa.us

INSPECTION REQUEST LINE: 509-962-7694

<http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx>

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506