INSPECTION REPORT

INST ECTION KET OKT			
PERMIT NUMBER:	BP-16-00729	OWNER'S NAME:	VILLAGE LLC
DATE:	5/12/2017	TYPE:	Insulation
TIME STARTED:	11:26 AM	INSPECTOR:	Justin Bennett
MAP NUMBER:	20-15-19056-0013		
3. Exterior insula	otalled behind fireplace - Ok etion - batt w/ vapor barrier on - batt w/ vapor barrier		
INSTRUCTIONS: O	k to cover		
RE-INSPECTION FEE	DUE2		\$
		DAID DDIOS TO 50115	
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
	QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL		
ADDRESS: <u>iustin.bennett</u> @co.kittitas.wa.us			

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506