INSPECTION REPORT

PERMIT NUMBER:	BP-16-00799	OWNER'S NAME:	ZAHNLE
DATE:	4/24/2017	TYPE:	Framing
TIME STARTED:	3:43 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-16-32050-0004		
LST18 straps to girts ok Install correct headers at man door and window per plan detail			
INSTRUCTIONS: O NEXT INSPECTION: RE-INSPECTION FEE	k to cover exterior Frame/final DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL			
	ADDRESS: <u>iessica.contratto</u> @co.kittitas.wa.us		

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506