## **INSPECTION REPORT**

INST ECTION KET OKT			
PERMIT NUMBER:	BP-17-00025	OWNER'S NAME:	MCDONALD
DATE:	5/11/2017	TYPE:	Multiple (see notes)
TIME STARTED:	10:34 AM	INSPECTOR:	Justin Bennett
MAP NUMBER:	17-19-06093-0002		
1. Exterior shear 2. HD's @ Porta	Ok I Framing not installed (4) - verify	at framing	
INSTRUCTIONS: O	k to cover Exterior  Plumb/Mech  DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL			
	ADDRESS:	iustin.bennett @	
		1401111101111011	

**INSPECTION REQUEST LINE: 509-962-7694** 

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506