INSPECTION REPORT

PERMIT NUMBER:	BP13-00679	OWNER'S NAME:	DUNN
DATE:	4/17/2015	TYPE:	Mechanical and plumbing
TIME STARTED:	12:12 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-16-27000-0001		
1. H2O o	k- live		
2. mechanical rough in -ok			
3. bath fans and range vent not in yet			
4. DWV on stack test- Leak in crawl and on upstairs shower drain			
5. maintain upward slope on vent array above kitchen area			
6. gas at 19#-ok			
INSTRUCTIONS: complete above, see at next inspection			
NEXT INSPECTION:	re-inspect DWV		
RE-INSPECTION FEE I	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
jessica.contratto @co.kittitas.wa.us			
• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506			