KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER:	FO-14-00050	**OWNER'S NAME:**	SOLE
DATE:	8/15/2014	**TYPE:**	Foundation walls
TIME STARTED:		**INSPECTOR:**	Amber Green
MAP NUMBER:	19-15-04054-0005		

	2. Re-bar in tall basement wall is required to have #4 vertical bar located 1" from insid
	e face of wall.
	4. Set and secure all hold-downs.
	6. Exterior pads not complete at this time.

INSTRUCTIONS: Complete above. OK TO POUR.

NEXT INSPECTION: SLAB

RE-INSPECTION FEE DUE? ☑ **NO** ☐ **YES** **$** _____

IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:

_____amber.green **@co.kittitas.wa.us**