INSPECTION REPORT

PERMIT NUMBER:	FO-14-00056	OWNER'S NAME:	BACK COUNTRY
DATE:	8/25/2014	TYPE:	Foundation walls
TIME STARTED:	10:56 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	19-15-07060-0005		
1. compa	ction test results on site-	-ok	
2. setbacks ok			
3. ok to p	our walls		
INSTRUCTIONS: OK	to pour walls		
NEXT INSPECTION:	floor framing		
RE-INSPECTION FEE I	DUE? NO YES		\$
IF REQU	UIRED, RE-INSPECTION FEES MUST BE	PAID PRIOR TO SCHE	DULING A RE-INSPECTION
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
jessica.contratto @co.kittitas.wa.us			
	TION REQUEST LINE: <u>www.co.kitti</u> 1 N. Ruby Street, Suite 2, Ellensburg, V		