INSPECTION REPORT

PERMIT NUMBER:	FO-14-00096	OWNER'S NAME:	MCBOYLE
DATE:	10/21/2014	TYPE:	Foundation walls
TIME STARTED:	2:35 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-15-19050-0061		
1. two hold downs missing at interior wall			
2. change out strap to STHD14 where indicated			
INSTRUCTIONS: complete above, ok to pour			
NEXT INSPECTION: floor framing			
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS: jessica.contratto @co.kittitas.wa.us			
INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 •			
411 N. Ruby Street, Suite 2. Ellensburg, WA 98926 • Main Office Line: 509-962-7506			