## **INSPECTION REPORT**

PERMIT NUMBER:	FO-14-00102	OWNER'S NAME:	CLIFTON
DATE:	1/7/2015	TYPE:	Foundation walls
TIME STARTED:	3:27 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-15-26063-0008		
1. ok to p	our walls		
2. see ex	terior pads later		
INSTRUCTIONS: se	e hold downs at framing		
NEXT INSPECTION:	exterior pads, floor framing		
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQ	UIRED, RE-INSPECTION FEES MUST BE	PAID PRIOR TO SCHE	DULING A RE-INSPECTION
QUI	ESTIONS? PLEASE CONTACT THE INSPE		
		ica.contratto @co.ki	
	<b>TION REQUEST LINE: <u>www.co.kitt</u></b> 1 N. Ruby Street, Suite 2, Ellensburg, V		