

## Kittitas County Fire Marshal's Office 411 N. Ruby St. Suite 2 Ellensburg, WA 98926 509-962-7657 Fax 509-962-7682

## FIRE LIFE SAFETY INSPECTION REPORT

Building/Business Owner Name:	(	ity of Ellensburg I	nspection Date: 2-22-16
Business Name: FIENSSORG 1	RAC	guet and Rec. Address: 6061	VANTAGE HWY
Inspection Issued To: DENN'S	5	Roserts Mailing Address: SA	amë
Type of Business: RECREATION	) (	Business phone number	ber: 509.925-8636
		your property. During this inspection conditi	
A. Exterior Assessment		E. Fire Alarm System	I. Kitchen Suppression
1 - Building number not posted		1 - Alarm Service Report	1 - Cleaning of hood and duct
2 - Obstructed FDC		2 - Devices obstructed	2 - Illegal cooking operation
3 - Obstructed fire hydrant		3 - Alarm Maintenance	3 - Six month service needed
4 - Gas meter protection		F. Flammable/Combustible Liquids	J. Automatic Sprinkler
5 - Storage proximity		1 - Storage cabinet	1 - Annual service needed
6 - Storage under eaves		2 - Improper housekeeping	2 - FDC cap needed
B. Exits		3 - No storage area	3 - Hanging material
1 - Exit travel		4 - Close to heating appliance	4 - Sprinkler clearance
2 - Exits obstructed		5 - Fueled equipment	5 - Provide sprinkler protection
3 - Panic hardware	_	6 - Oily rags	6 - Damaged/Painted heads
4 - Number of exits		7 - Compressed gas tanks	7 - Spare heads and/or wrench
5 - Unapproved locking devices		8 - Equipment rooms	K. Fuel Dispensing
C. Exit Lighting and Signs		G. Electrical	1 - Fire extinguisher
1 - Exit signs battery backup		1 - Extension cord usage	2 - Emergency shutoff
2 - Exit signs required		2 - Electrical panel labeling	3 - Provide signage
3 - Emergency lighting	X	3 - Portable heaters	4 - Replace hoses
4 - Exit sign burnt out	X	4 - Improper power strip usage	L. Hotel/Apartments
5 - "to remain unlocked" sign	7	5 - Panel obstructed	1 - Evacuation routes
D. Extinguishers		6 - No cover plate	2 - Fire alarm system
1 - Class K extinguisher		7 - Multi-plug adapter	3 - Smoke detectors
2 - Number of extinguishers			
3 - Extinguisher placement		H. Fire Walls and Doors	X. No Apparent Violations
4 - Extinguisher obstructed		1 - Restrained fire door	1 - No Apparent Violations
5 - Extinguisher maintenance	X	2 - Breached wall or ceiling	
6 - Signs indicating location	-	3 - Fire assembly needs repair	
Notes: 1 25 Mb 4 1/-R	0/1	Siches Essenti lette	Classes 1 - Classes 2 2000
NOTES. THE COLUMN AS A STATE OF THE COLUMN AS	4:15	Systems. Emergency right or	TOO PORMITORY TO SPORAGE ROOM
EXTENSING PERSON AND	~ A 1 A	1 socializades y Social Come	- Stairway to Sturage Room EEOS Replaced
Remarks:	10	10 MINTE 10 126 99 1000 1 2010	40
remarks.			
			his Fire Inspection reports also serves
			our invoice. Please remit payment in
		an	nount of \$ 640.00 within 30 days.
1 .			
Inspector: AS His	sk.	- DFM Received By	
mspecior.	*	Received by:	
. 0			Roberts DATE 2/22/16
SIGNATURE Lenna Kol	ier	PRINT NAME Dennis	Roberts DATE 2/22/16
Let to be desired to the second	1170		the second secon