03/04/2016 01:46:26 PM \$0.00 Claims Against County/rls/misc Kititas County Auditor	201603040039 Page: 1 of 8 PROSECUTER
i jarijar jijari iri ni njarin indini kar iral israa liins (aissin sia oli	<u>                                      </u>

PROSECUTOR GZ
COMMISSIONERS JK
DEPARTMENT MC
DISURANCE JP

### KITTITAS COUNTY CLAIM FOR DAMAGES

Return to: **County Auditor**205 W 5<sup>th</sup> Ave, Su

205 W 5<sup>th</sup> Ave, Suite 105 Ellensburg, WA 98926 509-962-7504

**Instructions:** 

Please read the entire form before completion. Fill out each question as completely as possible, to the best of your ability. Do not hesitate to use the back side of this form if you need more than the space provided. An incomplete response may delay the processing of your claim.

1.	Name (Including spouse, if married):  Greg A. Lutovsky
	Paige L. Anspach
2.	Phone (Home): ( ) (Work):
3.	Address (include former address if at present address for less than 6 months):
	Physical 7
	Mailing
4.	Date of Birth:
5.	Date and Time of Incident: 8:30-8:40 am 12/16/2015
6.	Location of Incident:  Kilmore Rd

Ş

And the driver dumptouck show plow and the driver dumptouck show plow and the driver dumptouck sand/grave That but my Audi R5 2015 all over hood root wines hield, grill, fenders  8. Describe in narrative form and in detail exactly how the incident occurred:  Greg + faige in Andi R5 following. Show plow truck on kilmone Rd pavement was bare & dry, weather was sunny. Truck had no sign or flacky lights that would have indivated that no was doing any type of work. I tried to pass twice was travelly only about 30-25 mph. Both times I for 9. List the names of all persons involved and contact information, if known.  Greg A. Intorsky - driver passing reform the man unknown.  Greg A. Intorsky - driver fame of the pass singer (ounty dumptruck showplow driver name unknown.)  10. Was claim investigated by a police officer? NO Sheriff State Patrol City Police  11. Description of claimant's vehicle: Audi Make 2015 Year Model: Q5 License No.  12. Describe what you did after the accident occurred: proceded to work and called my first wance Company two on their suggestion I call Paul Tewel to ask how the county handles such cistuchous	7.	Describe in detail the defect which caused the injury:
hit my Audi & 5 2015 all over hood root wines hield, 9vill, fenders  8. Describe in narrative form and in detail exactly how the incident occurred:  6reg + Paige in Andi & 5 following. Show plow truck on kilmone Rd pavement was bare & dry, we after was sunny, Truck had  NO sign or flacky lights that would have indivated that ne was doing any type of work. I tried to pass twice nee he was travelly only about 30-25 mph. Both times I to 9. List the names of all persons involved and contact information, if known.  Greg A. Lutorsky - driver  Paige L - Ansparh - passinger  County dumptruck showplow driver  Name unknown.  10. Was claim investigated by a police officer? NO  Sheriff State Patrol City Police  11. Description of claimant's vehicle: Audi Make 2015 Year  Model: Q S License No.  12. Describe what you did after the accident occurred:  proceded to work and called my Firswance Company		& following a county dumptruck snow plow
Wines hield, 9vill, fenders  8. Describe in narrative form and in detail exactly how the incident occurred:  Greg & Parge in Andi Q5 Following. Show plow truck on kilmone Rd  pavement was bare & dry, we after was sunny. Truck had  NO sign or flashy lights that would have indivated that  Ne was doing any type of work. I tried to pass twice  nee he was travelly only about 30-25 mph. Both fines I for  9. List the names of all persons involved and contact information, if known.  Greg A. Lutorsky - driver  Parge L- Auspach - passenger  County dumptruck Ishowplow driver  Name unknown.  10. Was claim investigated by a police officer? NO  Sheriff State Patrol City Police  11. Description of claimant's vehicle: Audi Make 2015 Year  Model: Q5 License No.  12. Describe what you did after the accident occurred:  proceded to work and called my Fusurance Company	Ü	and The driver dumped sand/grave That
8. Describe in narrative form and in detail exactly how the incident occurred:  Greg + Parge in Andi Q5 Following Show plow truck on Kilmone Rd pavement was bare & dry, we after was sunny. Truck had  NO sign or flashy lights that would have indivated that  Ne was doing any type of work. I tried to pass twice  nee he was travelly only about 30-25 mph. Both times I tri  9. List the names of all persons involved and contact information, if known.  Greg A. Lutorsky - driver  Gounty dum ptruck showplow driver  Name unknown.  10. Was claim investigated by a police officer? NO  Sheriff State Patrol City Police  11. Description of claimant's vehicle: Audi Make 2015 Year  Model: Q5 License No.  12. Describe what you did after the accident occurred:  Proceded to work and called my First wance Company		
Greg + Paige in Andi Q5 Following Show plow truck on Kilmone Rd pavement was bared dry, was fler was sunny. Truck had no sign or flashy lights that would have indicated that ne was doing any type of work. I tried to pass twice nee he was travelly only about 30-25 mph. Both times I truck he was travelly only about 30-25 mph. Both times I truck he was travelly only about 30-25 mph. Both times I truck he hames of all persons involved and contact information, if known.  Greg A Intorsky - driver  faige L - Ansparh - passenger  County dumptruck Ishowplow driver  Name unknown.  10. Was claim investigated by a police officer? NO  Sheriff State Patrol City Police  11. Description of claimant's vehicle: Audi Make 2015 Year  Model: Q5 License No.  12. Describe what you did after the accident occurred:  proceded to work and called my Inswance Company	0	· ·
pavement was baret dry, was fler was sunny. Truck had  NO sigh or flashylights that would have indicated that  No was doing any type of work. I tried to pass twice  not be was travelly only about 30-25 mph. Both times I for  9. List the names of all persons involved and contact information, if known.  Greg A. Lutorsky - driver  Parage L- Anspach - passinger  (ounty dumptruck/showplow driver  Name unknown.  10. Was claim investigated by a police officer? NO  Sheriff State Patrol City Police  11. Description of claimant's vehicle: Audi Make 2015 Year  Model: Q 5 License No  12. Describe what you did after the accident occurred:  Proceded to work and called my Insurance Company	8.	
NO Sign or flashy lights that would have indicated that  The was doing any type of work. I tried to pass twice  nee he was travelly only about 30-25 mph. Both times I tri  9. List the names of all persons involved and contact information, if known.  Greg A. Intorsky - driver  Parge L- Auspach - passinger  County dumptruck showplow driver  Name unknown.  10. Was claim investigated by a police officer? NO  Sheriff State Patrol City Police  11. Description of claimant's vehicle: Audi Make 2015 Year  Model: Q 5 License No.  12. Describe what you did after the accident occurred:  Proceeded to work and called my First wance Company	Greg	+ Paige in Andi Q5 tollowing. Snow plow truck on Kilmone Rd
Greg A. Lutorsky - driver  Parge L- Ansparh - passinger  County dumptruck Ishowplow driver  Name unknown.  10. Was claim investigated by a police officer? NO  Sheriff State Patrol City Police  11. Description of claimant's vehicle: Audi Make 2015 Year  Model: Q S License No.  12. Describe what you did after the accident occurred:  Proceded to work and called my Inswance Company	pavemen	it was bared dry, wrather was sunny. Truck had
Greg A. Lutorsky - driver  Parge L- Ansparh - passinger  County dumptruck Ishowplow driver  Name unknown.  10. Was claim investigated by a police officer? NO  Sheriff State Patrol City Police  11. Description of claimant's vehicle: Audi Make 2015 Year  Model: Q S License No.  12. Describe what you did after the accident occurred:  Proceded to work and called my Inswance Company	no sign	or flashy lights that would have indicated that
Greg A. Lutorsky - driver  Parge L- Ansparh - passinger  County dumptruck Ishowplow driver  Name unknown.  10. Was claim investigated by a police officer? NO  Sheriff State Patrol City Police  11. Description of claimant's vehicle: Audi Make 2015 Year  Model: Q S License No.  12. Describe what you did after the accident occurred:  Proceded to work and called my Inswance Company	1e was	doing any type of work. I tried to pass twice
Greg A. Lutorsky - driver  Parge L- Ansparh - passinger  County dumptruck Ishowplow driver  Name unknown.  10. Was claim investigated by a police officer? NO  Sheriff State Patrol City Police  11. Description of claimant's vehicle: Audi Make 2015 Year  Model: Q S License No.  12. Describe what you did after the accident occurred:  Proceded to work and called my Inswance Company	nce he u	as travelly only about 30-25 mph. Both times I tri
Parge L- Ausparh - passinger  County dumptruck Ishowplow driver  Name unknown.  10. Was claim investigated by a police officer? NO  Sheriff State Patrol City Police  11. Description of claimant's vehicle: Audi Make 2015 Year  Model: Q5 License No.  12. Describe what you did after the accident occurred:  Proceded to work and called my Firstmance Company	9.	List the names of all persons involved and contact information, if known.
Parge L- Ausparh - passinger  County dumptruck Ishowplow driver  Name unknown.  10. Was claim investigated by a police officer? NO  Sheriff State Patrol City Police  11. Description of claimant's vehicle: Audi Make 2015 Year  Model: Q5 License No.  12. Describe what you did after the accident occurred:  Proceded to work and called my Firstmance Company		Greg A. Lutorsky - driver .
County damptrack Showplow driver  Name unknown.  10. Was claim investigated by a police officer?		
10. Was claim investigated by a police officer?	••	
10. Was claim investigated by a police officer?		
Sheriff State Patrol City Police  11. Description of claimant's vehicle: Audi Make 2015 Year  Model: Q 5 License No  12. Describe what you did after the accident occurred:  proceded to work and called my Firstmance Company	:	
11. Description of claimant's vehicle: Audi Make 2015 Year  Model: Q 5 License No.  12. Describe what you did after the accident occurred:  proceded to work and called my Firstmance Company	10.	Was claim investigated by a police officer?
Model: Q5  License No.  12. Describe what you did after the accident occurred:  proceded to work and called my Firstmance Company	•	Sheriff State Patrol City Police
12. Describe what you did after the accident occurred:  proceded to work and called my Insurance Company	11.	Description of claimant's vehicle: Audi Make 2015 Year
proceeded to work and called my Firstrance Company		Model: Q 5 License No
proceeded to work and called my Firstrance Company	12	Describe what you did after the agaident accourad:
then on their suggestion I call paul Towel to	12.	ovaceded to work and calldown Inchance Company
and the suggestion I can paul jewer to		then a their acceptance T and Davit T
u(k) $v(u)$		ack how the country handles such cistuations
13. Describe the conversations you had, if any, with County personnel during or after the	13.	Describe the conversations you had, if any, with County personnel during or after the
I talked with Paul Tewel		I talked with Paul Tewel

shoulder to avoid him hitting me. of the voad. I had to down on grown 2m nul of p2/14 + ng 1/0 24 2mit = 2 24+ 10f 552d of p2,114 \$ 50 124100 of mitt & S521275 ON HIM 4.1 BIOUR of brist bup so the brakes as I saw the grovel/sand coming all our my Hudi BS. I slammed on the be hind him) He let go one with his gravel/sand coming corner, (I was about 100-125 feet qu mt vot nuob znimolz zow I zp type the scould not pass, Ather the second attempt to pass he faded over the centerline so

14.	Describe the damages or injuries which you sustained as a result of the incident:  Vock chips to grill, fenders, hood, wineshield
	and roof. see a Hacked
15.	What is the amount of damages claimed? (Include estimates and bills, if available):  891.58 See a Hacked estimates estimates
16.	How did you identify the County as the party responsible for your damage?  The was a county dump truck show ploud
17.	List the names and addresses of all witnesses to the incident:
Ċ	breg Lutousky
Pa	ign Anspach
•	
18.	Are you covered by insurance? Yes, who is your insurance agent/carrier?
S	herry Lynch @ Conover Ing - 509-989-5043 cell
of	herry Lynch @ Conover Ins-509-989-5043 cell ice 800-551-2090 Sherry was informed the day That it happined.
Dated	this Day of March, 2016.
	14 July
Signa	ture of Claimant
Subsc	cribed and sworn (affirmed) to before me this day of Mov, 20_16
Seal	Notary Public in and for the State of Washington Residing at E/(0) 600
	3 of 3

# R&R's ABRA Auto Body & Glass

Workfile ID: Federal ID:

e60079c4 91-1875401

641 WEST UNIVERSITY WAY, ELLENSBURG, WA 98926

Phone: (509) 925-5680 FAX: (509) 962-8741

### **Preliminary Estimate**

**Customer: Lutovsky, Greg** 

**Job Number:** 

Written By: Tom Morris

Insured:

Owner:

Lutovsky, Greg

Policv #:

Claim #:

Type of Loss:

Date of Loss:

Days to Repair:

Point of Impact:

Lutovsky, Greg

**Inspection Location:** 

**Insurance Company:** 

R&R's ABRA Auto Body & Glass 641 WEST UNIVERSITY WAY

ELLENSBURG, WA 98926

Repair Facility

(509) 925-5680 Business

### **VEHICLE**

Year:

Make:

2015

**AUDI** 

**Q5 AWD PRESTIGE** 

Body Style: Engine:

4D UTV

6-3.0L-TD

VIN: WA1VMAFP9FA106416 Mileage In: Mileage Out:

Vehicle Out:

Model: Color: Bahama Blue Int: Production Date:

Condition:

State: Job #:

License:

**Automatic Transmission** 

4 Wheel Drive

**TRANSMISSION** 

**POWER** 

**Power Steering Power Brakes Power Windows** Power Locks **Power Mirrors** 

**Heated Mirrors** Power Driver Seat Power Passenger Seat

Memory Package

**DECOR** 

**Dual Mirrors** Privacy Glass

Console/Storage Overhead Console **CONVENIENCE** 

Air Conditioning Intermittent Wipers

Tilt Wheel Cruise Control Rear Defogger

Keyless Entry Alarm

Message Center

Steering Wheel Touch Controls

Rear Window Wiper

Telescopic Wheel

Climate Control **Dual Air Condition** 

Navigation System

Backup Camera w/Parking Sensors

Home Link **RADIO** 

AM Radio

FM Radio Stereo

Search/Seek

CD Player Premium Radio

SAFETY

Drivers Side Air Bag Passenger Air Bag Anti-Lock Brakes (4)

4 Wheel Disc Brakes

Traction Control Stability Control

Front Side Impact Air Bags Head/Curtain Air Bags Rear Side Impact Air Bags

Hands Free Device Blind Spot Detection **ROOF** 

Luggage/Roof Rack Electric Glass Sunroof

Skyview Roof

**SEATS** 

**Bucket Seats** Leather Seats **Heated Seats** 

**WHEELS** 

Aluminum/Alloy Wheels

PAINT

Clear Coat Paint

**OTHER** 

Fog Lamps Rear Spoiler

Signal Integrated Mirrors

**TRUCK** 

Power Trunk/Gate Release

# **Preliminary Estimate**

# **Customer: Lutovsky, Greg**

Job Number:

Vehicle: 2015 AUDI Q5 AWD PRESTIGE 4D UTV 6-3.0L-TD Bahama Blue

Line		Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	FRONT BUM	PER & G	RILLE			•		
2			O/H bumper assy				3.5	
3		Repl	Grille w/o park sensors gloss black	8R0853651ALT94	1	675.00	Incl.	
4	* <>	Rpr	Bumper cover w/headlamp washer(repair rock chips)				<u>2.0</u>	3.2
5		Repl	LT Outer grille w/distance sensor, w/park sensor matte black	8R0807681SZDE	1	311.00	Incl.	
6		Repl	RT Outer grille w/distance sensor, w/park sensor matte black	8R0807682QZDE	1	· <b>355.00</b>	Incl.	
7	FRONT LAM	PS						
8		Repl	LT Headlamp assy	8R0941753E	1	1,049.00	1.0	
9			Aim headlamps				0.5	
10		Repl	RT Headlamp assy	8R0941754E	1	1,049.00	1.0	
11		Repl	RT Fog lamp assy	8T0941700B	1	121.00	0.3	
12		Repl	LT Fog lamp assy	8T0941699B	1	121.00	0.3	
13	HOOD							
14	*	Rpr	Hood				<u>1.5</u>	3.0
15			Overlap Major Non-Adj. Panel					-0.2
16	FENDER							
17	*	Rpr	RT Fender frm 11/15/2011				<u>1.0</u>	2.4
18			Overlap Major Adj. Panel					-0.4
19	*	Rpr	LT Fender frm 11/15/2011				<u>1.0</u>	2.4
20			Overlap Major Adj. Panel					-0.4
21		R&I	RT Lower molding w/o S-line pkg or SQ5				0.3	
22		R&I	LT Lower molding w/o S-line pkg or SQ5				0.3	
23	WINDSHIE	L <b>D</b>						
24		Repl	Windshield w/lane change assist NAGS	FW03822GTY	1	722.50	. 2.8	
25	ROOF							
26	*	Rpr	Roof panel				<u>2.0</u>	4.0
27			Overlap Major Non-Adj. Panel					-0.2
28		R&I	RT Roof molding chrome				0.4	
29		R&I	LT Roof molding chrome				0.4	
30		R&I	RT Luggage rack black				1.5	
31		R&I	R&I sunroof assy				1.8	
32	FRONT DOO	OR						
33	•	R&I	LT R&I mirror				0.4	
34		R&I	RT R&I mirror				0.4	
35	*	R&I	RT Mirror cover w/lane change pkg				0.3	
36	*	R&I	LT Mirror cover w/lane change				<u>0.3</u>	

## **Preliminary Estimate**

Custo	mer: Lutovsky, (	Greg				Job N	umber:
		Vehicle: 2015 AUDI Q5 AWD	PRESTIGE 4D UTV 6-3,0	L-TD Bahama	Blue		
		pkg					
37	Refr	RT Mirror cover w/lane change pkg					0.4
38		Overlap Minor Panel					-0.2
39	Refr	n LT Mirror cover w/lane change pkg					0.4
40		Overlap Minor Panel					-0.2
41		Clear Coat					2.5
42	R&I	RT R&I trim panel				0.6	
43	R&I	LT R&I trim panel				0.6	
44	QUARTER PANEL						
45	* Blnc	RT Quarter panel(painting roof no natrual break)					1.6
46	* Blnc	LT Quarter panell(painting roof no natrual break)					1.6
47	REAR LAMPS						,
48	R&I	RT Tail lamp assy				0.2	
49	R&I	LT Tail lamp assy				0.2	
50	REAR BUMPER						
51	R&I	R&I bumper assy				1.3	
52	MISCELLANEOUS C	PERATIONS					
53	#	`Car Cover		1	5.00	0.2	
54	# Rpt	Corrosion Protection					0.3
55	# Rpr	`Color Tint					0.5
56	# Sub	l `Hazardous Waste		1	5.00		
57	#	`Flex Additive/Adhesion Promoter		1	12.00		
	-		SUBTOTALS		4,425.50	26.1	20.7

### **ESTIMATE TOTALS**

Category	Basis		Rate	Cost \$	
Parts				4,425.50	
Body Labor	26.1 hrs	@	\$ 53.00 /hr	1,383.30	
Paint Labor	20.7 hrs	@	\$ 53.00 /hr	1,097.10	
Paint Supplies	21.9 hrs	@	\$ 31.00 /hr	678.90	
Subtotal				7,584.80	
Sales Tax	\$ 7,584.80	@	8.0000 %	606.78	
Grand Total				8,191.58	
Deductible				0.00	
CUSTOMER PAY	- · · -			0.00	
INSURANCE PAY				8,191.58	

IT IS A CRIME TO KNOWINGLY PROVIDE FALSE, INCOMPLETE, OR MISLEADING INFORMATION TO AN INSURANCE COMPANY FOR THE PURPOSE OF DEFRAUDING THE COMPANY. PENALTIES INCLUDE IMPRISONMENT, FINES, AND DENIAL OF INSURANCE BENEFITS.

### **Preliminary Estimate**

Customer: Lutovsky, Greg Job Number:

Vehicle: 2015 AUDI Q5 AWD PRESTIGE 4D UTV 6-3.0L-TD Bahama Blue

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide ERA1385, CCC Data Date 2/15/2016, and potentially other third party sources of data; and (b) the parts presented are OEM-parts manufactured by the vehicles Original Equipment Manufacturer, OEM parts are available at OE/Vehicle dealerships. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships. OPT OEM or ALT OEM parts may reflect some specific, special, or unique pricing or discount. OPT OEM or ALT OEM parts may include "Blemished" parts provided by OEM's through OEM vehicle dealerships. Asterisk (\*) or Double Asterisk (\*\*) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2016 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

### SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

### SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

### OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Information Services Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.