INSPECTION REPORT

OWNER'S NAME: SHIN

PERMIT NUMBER:	BP-10-00719	OWNER'S NAME:	SHIN
DATE:	8/6/2014	TYPE:	Final
TIME STARTED:		INSPECTOR:	Jessica Contratto
MAP NUMBER:	22-11-04051-0002		
1. open p	art of cricket structure to	verify framing	
2. replace non combustible ceiling and seal around duct with 3M fire caulking			
3. obtain fire marshal permit and necessary inspections for suppression system			
INSTRUCTIONS: ok to replace ceiling. Complete above, call for final			
NEXT INSPECTION: f	inal		
RE-INSPECTION FEE	OUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
jessica.contratto @co.kittitas.wa.us			
	TION REQUEST LINE: www.co.kitti N Ruby Street Suite 2 Ellensburg W		