INSPECTION REPORT

PERMIT NUMBER:	BP-10-00719	OWNER'S NAME:	SHIN
DATE:	9/10/2014	TYPE:	Mechanical
TIME STARTED:	11:28 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	22-11-04051-0002		
1. cricket	framing ok		
2. fire marshal signed off years prior			
3. duct is flashed and fire caulked			
INCTRUCTIONS: fin	al approved		
INSTRUCTIONS: fin	атарргочес		
NEXT INSPECTION:			
RE-INSPECTION FEE I	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
jessica.contratto @co.kittitas.wa.us			
• INSPECTION REQUEST LINE: <u>www.co.kittitas.wa.us/cds/request.asp</u> or 509-962-7694 • 411 N. Ruby Street, Suite 2. Ellensburg, WA 98926 • Main Office Line: 509-962-7506			