## **INSPECTION REPORT**

PERMIT NUMBER	: BP-13-00223	OWNER'S NAME:	DAUGHERTY
DATE:	9/25/2015	TYPE:	Re-inspection
TIME STARTED:	10:24 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	18-19-16000-0025		
1. seal/trir	m around door to shop, sho	op side	
2. seal holes in mechanical room wall where insulation is coming out (rodents?)			
3. blower door test ok			
4. blank covers 240v outlets in shop area			
5. seismic strapping on water heaters			
INSTRUCTIONS: complete above. Note: Door to shop area will have to be made self closing for change			
-	of use. Not necessary to fir	nal shop as is	
NEXT INSPECTION	re-inspect		
RE-INSPECTION FE	E DUE? NO	YES	\$
	EQUIRED, RE-INSPECTION FEES		
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
iessica.contratto @co.kittitas.wa.us			
	ECTION REQUEST LINE: <u>www.</u> 111 N_Ruby Street_Suite 2_Flle		