INSPECTION REPORT

OWNER'S NAME:

TYPE:

BP-13-00337

12/12/2014

PERMIT NUMBER:

DATE:

KLIPPA HUS LLC

Radiant heat

TIME STARTED:		12:24 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:		20-15-29050-0135		
	1. hydronics at 100#-ok			
INSTRUCTIONS: ok to pour				
NEXT INSPECTION:				
RE-INSPECTION FEE DUE? VES \$				
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION				
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:				
jessica.contratto @co.kittitas.wa.us				
• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506				
TIT IV. Nuby Street, Suite 2, Literisburg, WA 30320 Viviani Office Line. 303-302-7300				