## **INSPECTION REPORT**

BP-13-00339

**PERMIT NUMBER:** 

OWNER'S NAME: MCINTOSH

DATE:		3/26/2015	TYPE:	Final
TIME STARTED:		12:06 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:		18-18-08020-000	2	
	2. Ductle	ess heat pumps install	ed without permi	ttina
	3. fresh air not ducted to woodstove			
	4. plumbing ok			
	•			
INSTRUCTIONS: complete above, secure mechanical permit for heat pumps, call for re-inspection				
NEXT INSPECTION: re-inspection				
RE-INSPECTION FEE DUE? VES \$				
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION				
	Ql	JESTIONS? PLEASE CONTACT THE	INSPECTOR AT THE FOLLO jessica.contratto @co.	
• INSPECTION REQUEST LINE: <a href="www.co.kittitas.wa.us/cds/request.asp">www.co.kittitas.wa.us/cds/request.asp</a> or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506				