INSPECTION REPORT

PERMIT NUMBER: BP-13-00367 OWNER'S NAME: ELLIS

DATE:	6/5/2015	TYPE:	Radiant heat
TIME STARTED:	11:07 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-14-24050-0106		
1. hydroni	cs at 100#-ok		
INSTRUCTIONS: ok to pour floor			
NEXT INSPECTION: exterior insulation panels			
RE-INSPECTION FE	E DUE? NO	YES	\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
iessica.contratto @co.kittitas.wa.us			
	ECTION REQUEST LINE: www.co 11 N. Ruby Street, Suite 2, Ellensbu		<u> </u>