## **INSPECTION REPORT**

OWNER'S NAME: ELLIS

PERMIT NUMBER: BP-13-00367

DATE:	7/27/2015	TYPE:	Insulation	
TIME STARTED:	1:41 PM	INSPECTOR:	Jessica Contratto	
MAP NUMBER:	20-14-24050-0106			
1. exterior	insulation ok R-8			
INSTRUCTIONS: ok to cover exterior				
NEXT INSPECTION:				
RE-INSPECTION FEE DUE? VES \$  IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION				
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:				
iessica_contratto @co.kittitas.wa.us				
	ECTION REQUEST LINE: <a href="www.co.">www.co.</a> 11 N. Ruby Street, Suite 2, Ellensburg			