## **INSPECTION REPORT**

PERMIT NUMBER:	BP-13-00369	OWNER'S NAMI	ELLIS
DATE:	7/23/2014	TYPE:	Foundation walls
TIME STARTED:	1:04 PM	INSPECTOR:	Amber Green
MAP NUMBER:	20-14-24050-0106		
1. Provid	de engineered detail for	tall retaining v	wall to the south.
Fireplace	e not complete at this tir	ne, will see at	later inspection.
INSTRUCTIONS: O	K TO POUR. PROVIDE ENGIN	EERED CHANGES	, WITH NEW FOUNDATION LAYOUT.
NEXT INSPECTION:	FIREPLACE WALLS		
RE-INSPECTION FEE	DUE? NO Y	ES	\$
IF REQ	UIRED, RE-INSPECTION FEES MUST	BE PAID PRIOR TO SC	HEDULING A RE-INSPECTION
QU	ESTIONS? PLEASE CONTACT THE INS		
	amber.green		.kittitas.wa.us
	<b>CTION REQUEST LINE: <u>www.co.ki</u></b> 1 N. Ruby Street, Suite 2, Ellensburg		<del></del>