INSPECTION REPORT

PERMIT NUMBER: BP-13-00369 OWNER'S NAME: ELLIS

DATE:		6/5/2015	TYPE:	Radiant heat	
TIME STARTED:		11:14 AM	INSPECTOR:	Jessica Contratto	
MAP NUMBER:		20-14-24050-0106			
	1. hydronics	cs at 100#-ok			
INSTRUCTIONS: ok to pour floor					
NEXT INSPECTION: exterior insulation					
RE-INSPECTION FEE DUE? VES \$					
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION					
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:					
iessica.contratto @co.kittitas.wa.us					
• INSPECTION REQUEST LINE: <u>www.co.kittitas.wa.us/cds/request.asp</u> or 509-962-7694 •					
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506					