## **INSPECTION REPORT**

PERMIT NUMBER:	BP-13-00397	OWNER'S NAME:	GRINNELL
DATE:	10/8/2014	TYPE:	Frame-Plumb-Mech
TIME STARTED:	4:24 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-16-26000-0038		
1. DWV a	at 5#/15 min- ok		
2. gas at	15#-ok		
3. mecha	nical ok		
4. Draft stop required for walls exceeding 10 in height			
5. truss bracing missing on D4			
INSTRUCTIONS: complete above, see at insulation			
	<u>'</u>		
NEXT INSPECTION:	insulation		
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQ	UIRED, RE-INSPECTION FEES MUST BE	PAID PRIOR TO SCHE	DULING A RE-INSPECTION
QU	ESTIONS? PLEASE CONTACT THE INSPI		
	jess	ica.contratto @co.ki	ttitas.wa.us
	TION REQUEST LINE: <a href="www.co.kitt">www.co.kitt</a> 1 N. Ruby Street, Suite 2, Ellensburg, V		