KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER:	BP-13-00657	**OWNER'S NAME:**	SCHMIDT
DATE:	8/8/2014	**TYPE:**	Final
TIME STARTED:	12:17	**INSPECTOR:**	Mike Flory
MAP NUMBER:	17-18-08058-0004		

	1. SEAL ALL PENETRATIONS IN GARAGE WITH FIRE CAULK
	2. ALL ELECTRICAL IN GARAGE TO HAVE COVER PLATES INSTALLED
	3. VOID TO LEFT SIDE OF FURNACE TO BE COVERED
	4. KITCHEN HOOD TO EXHAUST OUTSIDE
	5. LOOSE FIBERGLASS INSULATION IN GAS F.P. CAVITY - CLEAN OUT
	6. GAS FIREPLACE MUST OPERATE
	7. GAS RANGE DOES NOT LIGHT - MUST OPERATE
	8. PERMIT CARD NOT ON SITE
	9. VERIFY SEPTIC AND ACCESS ARE SIGNED OFF

INSTRUCTIONS: FIX ABOVE AND RECALL FOR RE-INSPECTION

NEXT INSPECTION: RE-FINAL

RE-INSPECTION FEE DUE? ☑ **NO** ☐ **YES** **$** _____

IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:

_____mike.flory **@co.kittitas.wa.us**