



KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER: BP-14-00009 OWNER'S NAME: LARSEN
 DATE: 8/27/2014 TYPE: Final
 TIME STARTED: 1:18 PM INSPECTOR: Jessica Contratto
 MAP NUMBER: 20-14-12054-0014

1. Install outlet covers
2. complete and insulate range vent
3. access and sewer need to be signed off on permit card
4. fireplace not functioning
5. submit plan revision for added bathroom in garage
6. blower door test not completed. post results within 3ft of electrical panel
7. range to be installed and functioning

INSTRUCTIONS: complete above, call for re-inspection

NEXT INSPECTION: re-inspection

RE-INSPECTION FEE DUE? NO YES \$ _____
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:

_____ [jessica.contratto @co.kittitas.wa.us](mailto:jessica.contratto@co.kittitas.wa.us)

• **INSPECTION REQUEST LINE:** www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 •
 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506