## **INSPECTION REPORT**

PERMIT NUMBER:	BP-14-00045	OWNER'S NAME:	CHAPIN
DATE:	8/27/2014	TYPE:	Insulation
TIME STARTED:	2:32 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	19-15-12000-0046		
1. Pendin	g L&I approval for cover		
2. Add LUSS28 hangers at rafter to ledger connection			
3. 2X10 blocking at 24" first 2 joist bays in floor			
4. insulat	ion ok		
INSTRUCTIONS: complete above. call for re-inspection after L&I approval for cover.			
NEXT INSPECTION:	e-inspection		
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
jessica.contratto @co.kittitas.wa.us			
• INSPECTION REQUEST LINE: <a href="www.co.kittitas.wa.us/cds/request.asp">www.co.kittitas.wa.us/cds/request.asp</a> or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506			