## **INSPECTION REPORT**

PERMIT NUMBER:	BP-14-00045	OWNER'S NAME:	CHAPIN
DATE:	10/31/2014	TYPE:	Final
TIME STARTED:	10:53 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	19-15-12000-0046		
1. final of	<b>(</b>		
2. send p	ic of countertops installe	ed	
INSTRUCTIONS: fin	al ok		
NEXT INSPECTION:	N/A		
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQ	UIRED, RE-INSPECTION FEES MUST BE	PAID PRIOR TO SCHE	DULING A RE-INSPECTION
QUI	ESTIONS? PLEASE CONTACT THE INSPI jess	ECTOR AT THE FOLLOW ica.contratto @co.k	
	TION REQUEST LINE: <a href="www.co.kitt">www.co.kitt</a> 1 N. Ruby Street, Suite 2, Ellensburg, V		