INSPECTION REPORT

TYPE:

PERMIT NUMBER:

DATE:

BP-14-00051

11/25/2014

OWNER'S NAME: CITY OF EBURG

Slab

TIME STARTED:	9:54 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	18-18-25068-0046		
1. gene	rator pad ok to pour		
INSTRUCTIONS: (ok to pour		
NEXT INSPECTION:	slab insulation, mesh		
RE-INSPECTION FE	E DUE? NO YE	S	\$
IF RE	QUIRED, RE-INSPECTION FEES MUST B	E PAID PRIOR TO SO	CHEDULING A RE-INSPECTION
Q	UESTIONS? PLEASE CONTACT THE INSP		
		sica.contratto @c	
	CTION REQUEST LINE: www.co.kit 11 N. Ruby Street, Suite 2, Ellensburg,		
	-		