INSPECTION REPORT

PERMIT NUMBER:

BP-14-00055

OWNER'S NAME: STEVE BURNSTEAD CONST.

DATE:	10/14/2014	TYPE:	Exterior shear
TIME STARTED:	2:25 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-15-20059-0012		
1. exteri	or shear ok		
INSTRUCTIONS: ok to cover			
NEXT INSPECTION:	frame/plumb/mech		
RE-INSPECTION FEI	E DUE?		\$ THEDULING A RE-INSPECTION
Q	UESTIONS? PLEASE CONTACT THE INSP		
		sica.contratto @co	
	ECTION REQUEST LINE: www.co.kit 11 N. Ruby Street, Suite 2, Ellensburg,		