INSPECTION REPORT

PERMIT NUMBER:	BP-14-00069	OWNER'S NAME:	JANKER
DATE:	8/11/2014	TYPE:	Framing
TIME STARTED:		INSPECTOR:	Jessica Contratto
MAP NUMBER:	19-15-07058-0007		
1. Nail P	4 and P3 shearwalls per	schedule	
2. Framir	ng and trusses ok		
INSTRUCTIONS: CO	mplete above, call for re-inspec	tion	
NEXT INSPECTION:	re-inspect shear		
RE-INSPECTION FEE	DUE? NO YES	·	\$
	UIRED, RE-INSPECTION FEES MUST BE		
QU	ESTIONS? PLEASE CONTACT THE INSPE jess	ECTOR AT THE FOLLOW ica.contratto @co.k	
	TION REQUEST LINE: www.co.kitt 1 N. Ruby Street, Suite 2, Ellensburg, V		