## **INSPECTION REPORT**

PERMIT NUMBER:	BP-14-00096	OWNER'S NAME:	KCFD #7
DATE:	11/12/2014	TYPE:	Slab
TIME STARTED:	10:29 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-14-26040-0005		
1. rebar o	ok in apparatus bays		
INSTRUCTIONS: OK	to pour		
NEXT INSPECTION:			
RE-INSPECTION FEE	DUE? NO YES		\$
	UIRED, RE-INSPECTION FEES MUST BE		
QUI	ESTIONS? PLEASE CONTACT THE INSPI		
• INSDEC	TION REQUEST LINE: www.co.kitt	ica.contratto @co.ki	
	I N Ruby Street Suite 2 Ellensburg V		