KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER:	BP-14-00096	**OWNER'S NAME:**	KCFD #7
DATE:	12/18/2014	**TYPE:**	Multiple (see notes)
TIME STARTED:	11:37 AM	**INSPECTOR:**	Jessica Contratto
MAP NUMBER:	20-14-26040-0005		

	1. firewall parallel to purlins ok
	2. GWB does not go to roofing on wall perpendicular to purlins
	3. no deflection track installed in perpendicular wall??

INSTRUCTIONS: complete above, do not cover perp. wall. Call for re-inspection

NEXT INSPECTION: re-inspection

RE-INSPECTION FEE DUE? ☑ **NO** ☐ **YES** **$** _____

IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:

_____jessica.contratto **@co.kittitas.wa.us**