KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER:	BP-14-00381	**OWNER'S NAME:**	PARR
DATE:	10/31/2014	**TYPE:**	Framing
TIME STARTED:	1:27 PM	**INSPECTOR:**	Jessica Contratto
MAP NUMBER:	20-15-19050-0046		

	1. post down under dormer girder trusses in bonus room (4 places)

INSTRUCTIONS: complete above, see at insulation

NEXT INSPECTION: insulation

RE-INSPECTION FEE DUE? ☑ **NO** ☐ **YES** **$ _____**

IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:

_____jessica.contratto **@co.kittitas.wa.us**