KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

# INSPECTION REPORT

| | | | |
|---|---|---|---|
| **PERMIT NUMBER:** | BP-14-00390 | **OWNER'S NAME:** | BADDA |
| **DATE:** | 10/16/2014 | **TYPE:** | Frame-Plumb-Mech |
| **TIME STARTED:** | 10:37 AM | **INSPECTOR:** | Jessica Contratto |
| **MAP NUMBER:** | 20-16-14000-0002 | | |

| | |
|---|---|
| | 1. H2O at 80#- ok |
| | 2. DVW on stack- ok |
| | 3. insulation behind showers on exterior walls to be R-21 |
| | 4. insulation behind shower to be face stapled to studs |
| | 5. secure tub flanges |
| | 6. truss bracing in progress. check at insulation |
| | |
| | |
| | |
| | |
| | |
| | |
| | |

**INSTRUCTIONS:** see corrections at insulation. Ok to insulate

**NEXT INSPECTION:** insulation

**RE-INSPECTION FEE DUE?** ☑ **NO** ☐ **YES** **$ _____**

***IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION***

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:

_____jessica.contratto **@co.kittitas.wa.us**