KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER:	BP-14-00514	**OWNER'S NAME:**	CARINO
DATE:	5/7/2015	**TYPE:**	Framing
TIME STARTED:	12:16 PM	**INSPECTOR:**	Jessica Contratto
MAP NUMBER:	20-15-19051-0049		

	1. bearing at mid span on PSL in upstairs bumpout
	2. no outlooker detail provided
	3. fireplace ok

INSTRUCTIONS: ok to insulate, see corrections then

NEXT INSPECTION: insulation

RE-INSPECTION FEE DUE? ☑ **NO** ☐ **YES** **$** _____

IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:

jessica.contratto **@co.kittitas.wa.us**